

ACC Monitoring Agency

6555 Penn Avenue, Pittsburgh, PA 15206

<https://acc-ma.org>

Services Provided By:



A Program of ASTM International

Memorandum: 12-1

Date: May 14, 2012

To: ACC Monitoring Agency Users

From: Donald Lind

SUBJECT: Termination of Sequence IIIGB Test

A test Sponsor posed this question to the ACC Monitoring Agency: "If a Test Sponsor registers both a Seq. IIIG and IIIGB test with the same formulation stand code and the Seq. IIIG is a failure, does the Sponsor still have to conduct the IIIGB phosphorus retention measurement on the used oil.

A Seq. IIIGB test may be terminated at Test Sponsor request when the registered Seq. IIIG test has been determined to be a fail. The Declarations for the Seq. IIIGB test must state that the test was "terminated at sponsor request" with a comment that this was done due to failure of the Seq. IIIG test.

DML/dml

cc: Doug Anderson, ACC

Distribution: email