

Status Of Reported Tests

STATUS	COUNT	PERCENT
Aborted	2	5.128
Valid	37	94.872
Total Reported Tests	39	100.000

Itemized Lost Test Report

Obs	Date	TESTKEY	REASON
1	20240624	ACC-36128	Test Aborted Due To Temp Controller Issue Causing Head Gasket Failure.
2	20240816	ACC-36655	Test Aborted Due To Oil Leak

Replicate Database Report

Components of Replicate Database	OCT 2024	All Periods
Number of Tests	.	107
Formulations	.	43
Labs	.	3
Stands	.	9

by-Formulation Pooled s and Reproducibility of Replicate Data

Report Period	Parameter	Degrees of Freedom	Pooled s	R
All	BWL	64	11.7338	32.8548
All	BWL (Without SA)	64	11.6788	32.7005

Pass/Fail
BWL <=26.0

Report Period	API Category	N	Number Passed	% Passed
OCT 2024	All Categories, All Parameters	37	33	89.1892
OCT 2024	SN - All Parameters	37	33	89.1892
OCT 2024	SN, BWL	37	33	89.1892
OCT 2024	SN, BWL (Without SA)	37	33	89.1892
All	All Categories, All Parameters	2471	2046	82.8005
All	SN - All Parameters	2471	2046	82.8005
All	SN, BWL	2471	2046	82.8005
All	SN, BWL (Without SA)	2471	2024	81.9102

ACC Monitoring Agency

203 Armstrong Drive, Freeport, PA 16229, USA

<https://www.acc-ma.org>
412-365-1000


Services provided by:



A Program of ASTM International

VIII

Status of Reported Tests



ACC Monitoring Agency

203 Armstrong Drive, Freeport, PA 16229, USA

<https://www.acc-ma.org>
412-365-1000

Services provided by:



A Program of ASTM International

VIII

Candidate Precision as Represented by Pooled S

